



West Visayas State University

JANIUAY CAMPUS

PHYSICAL PLANT & FACILITIES SUPERVISOR'S OFFICE

(Formerly Janiuay Polytechnic College, Don Tiburcio A. Luterio National Comp. High School, Janiuay Nat'l Comp. High School, Janiuay National Vocational High School, Janiuay High School)

Janiuay, Iloilo, Philippines

*Trunkline: (063) (033) 330-3485

* Website: www.wvsu.edu.ph *Email Address: januiay@wvsu.edu.ph



SCOPE OF WORKS

No. 2024-05

Project Title : **IMPROVEMENT OF FLOORING OF THE CAMPUS GYMNASIUM.**

Location : **WVSU-Janiuay Campus
Locsin Street, Janiuay, Iloilo**


ITEMS:

- 1. Repair, Retouching, Smoothing, and Leveling of Existing Damaged Concrete Flooring:** This involves a thorough assessment of the current condition of the concrete flooring within the designated area. Any cracks, chips, or other forms of damage will be identified and addressed through appropriate repair techniques. This may include filling in cracks, patching damaged areas, and smoothing out uneven surfaces to create a level foundation. The goal is to restore the integrity of the flooring, ensuring it is structurally sound and aesthetically pleasing.
- 2. Repainting of the Concrete Flooring:** Once the necessary repairs have been completed and the surface has been properly prepared, the next step is to repaint the concrete flooring. This involves the application of high-quality concrete paint or epoxy coatings to provide a durable and visually appealing finish.
- 3. Housekeeping Works:** Following the completion of repair and maintenance tasks, thorough housekeeping works will be conducted to ensure the area is clean, organized, and ready for use. This may include sweeping, mopping, dusting, and disinfecting surfaces, as well as removing any debris or waste materials.

REPAIRED BY:


JAN-NC A. ALINSASAGUIN, UAP
Campus Architect

NOTED BY:


EMMANUEL M. SALAMANCA, Ed.D
Supervisor, CPPO