



# West Visayas State University

JANIUAY CAMPUS

**PHYSICAL PLANT & FACILITIES SUPERVISOR'S OFFICE**  
(Formerly Janiuay Polytechnic College, Don Tiburcio A. Lutero National  
Comp. High School, Janiuay Nat'l Comp. High School, Janiuay National  
Vocational High School, Janiuay High School)

Janiuay, Iloilo, Philippines

\*Trunkline: (063) (033) 330-3485

\* Website: [www.wvsu.edu.ph](http://www.wvsu.edu.ph) \*Email Address: [janiuay@wvsu.edu.ph](mailto:janiuay@wvsu.edu.ph)



## SCOPE OF WORKS No. 2022-05

**Project Title** : REPAIR AND REHABILITATION OF THE BAGONG LIPUNAN BUILDING.  
**Location** : WVSU-Janiuay Campus  
Locsin Street, Janiuay, Iloilo


### ITEMS:

1. Demolition/removal of damaged portion of the ceiling.
2. Removal of old and damaged wood jalousie windows.
3. Removal of the old and damaged wood doors.
4. Concrete topping of the damaged flooring.
5. Repair of ceiling.
6. Repair of wood partitions.
7. Installation of new glass jalousie windows.
8. Installation of new wood doors and accessories.
9. Installation of new fascia cover.
10. Repair/Patching of leaking roof.
11. Painting of walls, ceiling and roof.
12. Housekeeping works.

REPAIRED BY:

  
ARCH. JAN N. A. ALINSASAGUIN  
Campus Architect

NOTED BY:

  
EMMANUEL M. SALAMANCA, Ed.D  
Supervisor, CPPO